
PROGRESS REPORT PHOTOS







2. Excavation of grade beams for slab on grade