

PROGRESS REPORT PHOTOS



1. Erection of PEMB frame



2. Erection of PEMB frame



3. Erection of PEMB frame



4. Erection of PEMB roof framing



5. Installation of electrical provider service pole



6. PEMB frame

PROGRESS REPORT PHOTOS (2)



7. *Installation of PEMP wall sheathing*



8. *Installation of PEMB roof sheathing*



9. *Installation of security gates at abandoned R.O.W.*