

PROGRESS REPORT PHOTOS



1. Pretreat of subgrade for termites



2. Installation of vapor barrier



3. Excavation of grade beams



4. Grade beam reinforcing steel placement



5. Trench drain subgrade excavation



6. Installation of fence post at large animal area