

**PROGRESS REPORT PHOTOS**



1. *Installation of livestock soil at Large Animal area*



2. *PEMB trim at Large Animal area*



3. *Sliding door installation at Small Animal area*



4. *PEMB dividing wall*



5. *Sliding doors at west elevation*



6. *PEMB at north elevation*