

PROGRESS REPORT PHOTOS



1. HVLS fan installation



2. Plywood and partitions in hay storage



3. Site sanitary piping



4. Site domestic water piping thrust block



5. Animal pen delivery



6. Interior plywood and trim at Storage Pens

PROGRESS REPORT PHOTOS (2)



7. MEP systems for animal pens



8. MEP systems for animal pens



9. Hardi trim at classroom