

PROGRESS REPORT PHOTOS



1. *Installation of bird screens at sliding doors*



2. *Installation of bird screens at sliding doors*



3. *Painting of finish carpentry above restrooms*



4. *Concrete walk at front elevation*



5. *Excavation of drainage swale on west property line*



6. *Excavation of drainage swale on north property line*

PROGRESS REPORT PHOTOS (2)



7. *Delivery of fencing materials*



8. *Drainage swale on north property line*



9. *Placement of fill for final grade*